## **HAZARD REPORT**

Hazard Report			
Task: heading out for a smoke	Location: East shop door		Date: Feb 12th 2013
Completed By: Phil	Reported To: ☐ in person ☐ by phone ☐ by email ☐ other		Time: About 9:05
Risk Assessment Legend: (Circle the class appropriate	Class A Hazard: Immediately stop work. Eliminate the hazard if possible. If not, contact Site Supervisor.		
to the hazard)	Class B Hazard: Immediately stop work. Introduce new control measures. Notify Site Supervisor immediately.		
Class C Hazard: Record hazard and existing control measures. Notify Site Supervisor by end of shift.			res. Notify Site
New Hazard(s)	<b>Existing Controls</b>	New Controls	Approved By
Ice has formed outside of shop door	I threw sand on it from the bucket.	Suggested to Super that we get the damaged downspout replaced.	Wendy Dai
Management Follow-Up	Completed By: Wendy Dai		<b>Date:</b> Feb 13th, 2012
Comments: I have requested a quote from ABC Construction to get the gutter and downspout repaired around the exit.			